1 st & part

No.....
Division Dasarahalli

Original/Duplicate/Triplicate
CONTRACT CERTIFICATE
(For Other Works)

Date

Work code No:

| INSPECTION REPORT | |
|---|---|
| Name of work | WARD MAINTANANCE IN Bagalagunte Ward No 14 2.00 PM to 10.00 PM |
| BR No | 529/30-8-2014 |
| Agency | Jayamma K |
| Work order No | BBMP/DZ/EE/DD/WO/200/13-14 Dated:-9-1-2014 |
| Est Amount | 12.00 Lakh |
| Bill Amount | 758839 |
| Job code | 014-14-000027 |
| P code | 1771 |
| Date of Inspection | 04-03-2016 |

The above said work was shown to me by the Concerned Ward Engineer

The work is inspected by me along with the Concerned Ward Engineer. and verified the records.

The work done is Satisfactory

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ ಕಛೇರಿ
ಟಿ. ದಾಸರಹಳ್ಳಿ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು - 560 073.

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara Palike
Dasarahalli Division, Bangalore-73

Scanned by CamScanner